



8853 E Desert Verbena  
Tucson, AZ 85715  
/ [www.dallasairmotive.com](http://www.dallasairmotive.com)



### FEATURES/HIGHLIGHTS

- Engine Maintenance Program
- CESCOM (Cessna Computerized Maintenance Tracking Program)
- RVSM
- Terrain Awareness & Warning System
- Traffic Collision Avoidance System
- SATCOM
- Cockpit Voice Recorder
- Flight Management System
- 8.33 channel spacing
- FM immunity
- Freon Air Conditioning

8853 E Desert Verbena  
Tucson, AZ 85715  
/ [www.dallasairmotive.com](http://www.dallasairmotive.com)


**AIRFRAME**

<b>Year Mfr/Div:</b>	2002 / 2002
<b>Registration #:</b>	N85JV [Expires: 6/30/2019]
<b>Purchase Date:</b>	2/13/2015
<b>Airframe Total Time:</b>	4,536 hrs (As of 1/6/2015)
<b>Landings/Cycles:</b>	3,329
<b>New/Used:</b>	Previously Owned
<b>Location:</b>	SCF - KSDL - Scottsdale Airport, Scottsdale - AZ - United States

**ENGINE(S)**

<b>Model:</b>	FJ44-2C
<b>On Condition TBO:</b>	No
<b>Maintenance Program:</b>	Williams International - TAP - Elite
<b>Ser No:</b>	Eng 1 (L): 126037 / Eng 2 (R): 126038
<b>Total Time Since New:</b>	Eng 1 (L): 4,536 hrs / Eng 2 (R): 4,536 hrs
<b>Time Between Overhaul:</b>	Eng 1 (L): 3,500 hrs / Eng 2 (R): 3,500 hrs
<b>Cycles Since New:</b>	Eng 1 (L): 3,329 hrs / Eng 2 (R): 3,329 hrs

8853 E Desert Verbena  
Tucson, AZ 85715  
/ [www.dallasairmotive.com](http://www.dallasairmotive.com)




### AVIONICS

<b>ADF:</b>	Honeywell KR-87
<b>Avionics Package:</b>	Collins Pro Line 21 2-tube / Silver Crown
<b>Communication Radios:</b>	Dual Honeywell KY-196B w/8.33 spacing
<b>CVR:</b>	CVR
<b>DME:</b>	Honeywell KN-63
<b>EFIS:</b>	Collins Pro Line 21 2-tube
<b>Flight Director:</b>	Collins Pro Line 21 2-tube
<b>Flight Rules:</b>	IFR
<b>FMS:</b>	Universal UNS-1K
<b>Hi Frequency:</b>	Yes
<b>Navigation Radios:</b>	Dual Honeywell KN-53 w/FM immunity
<b>Radar Altimeter:</b>	Collins ALT-55B
<b>SATCOM:</b>	AirCell ST-3100
<b>TAWS:</b>	Honeywell Mark VII EGPWS
<b>TCAS:</b>	Honeywell TCAS-II
<b>Transponder:</b>	Dual Honeywell MST-67A Mode S
<b>Weather Radar:</b>	Collins RTA-800

### ADDITIONAL EQUIPMENT

<b>Cockpit:</b>	AirCell ST-3100 SATCOM, Artex C406-2 ELT, Garmin GMX-200 multi-function display, WSI
<b>Crew Accessories:</b>	ChartView
<b>Equipment:</b>	Lead acid battery

8853 E Desert Verbena  
Tucson, AZ 85715  
/ [www.dallasairmotive.com](http://www.dallasairmotive.com)




### INTERIOR

<b>Last Done:</b>	2009
<b>Passengers:</b>	7
<b>Configuration:</b>	Executive
<b>General:</b>	Interior deep cleaned 06/14 by Classic Interior
<b>Seating:</b>	4-place club, dual forward-facing chairs; seating touched up 06/14 by Classic Interior, recovered seat covers by Duncan Aviation as reported 01/06/15
<b>Carpet:</b>	New carpeting installed 06/14 by Duncan Aviation
<b>Refreshment Equip:</b>	Forward refreshment center
<b>Cabinetry/Woodwork:</b>	Pullout executive tables
<b>Accessories:</b>	Recovered panels & bulkheads by Duncan Aviation as reported 01/06/15
<b>Lavatory:</b>	Aft

### EXTERIOR

<b>Last Done:</b>	Duncan Aviation on 2009
<b>Colors:</b>	Snow white w/blue, platinum & red
<b>General:</b>	Sherwin Williams snow white stripped w/Dupont dark blue effect, platinum effect & Seminole red; gray landing gear

8853 E Desert Verbena  
Tucson, AZ 85715  
/ [www.dallasairmotive.com](http://www.dallasairmotive.com)




### MAINTENANCE

<b>Maintained:</b>	FAR Part 135
<b>Airframe Maint Program:</b>	ProParts
<b>Airframe Tracking Program:</b>	CESCOM (Cessna Computerized)
<b>Certification(s):</b>	RVSM
<b>Notes:</b>	RVSM; up-to-date as reported 01/06/15. Aircraft is enrolled on Cessna ProTech & ProParts. Engine Hot Section inspections due at LE/RE: 5830TT / 5830TT. Engine overhauls due at LE/RE: 7830TT / 7830TT.; Document 10 & 11 inspections c/w 05/13 by Cessna, Orlando, FL. Document 1 & 2 inspections due 05/15. Maintained by Cessna service centers. All AD's & SB's current as reported 01/06/15. One owner since new.

### MAINTENANCE ITEMS

	C/W	C/W Hrs	Due	Due Hrs	Notes
<b>Document 1 Inspection:</b>			05/15		& 2 inspections
<b>Engine Overhaul:</b>				7830	LE
<b>Document 1 Inspection:</b>	05/13				& 11 inspections by Cessna, Orlando, FL
<b>Document 10 Inspection:</b>	05/13				& 11 inspections by Cessna, Orlando, FL

8853 E Desert Verbena  
Tucson, AZ 85715  
/ [www.dallasairmotive.com](http://www.dallasairmotive.com)



---

**COMPANY/CONTACTS**

---

**Owner** - SWD Buck, LLC  
8937 E Bell Road, Ste. 100  
Scottsdale, AZ 85260  
Office : 602-667-3145  
Fax : 602-667-3158

**Mr. Scott Pfeiffer**  
Manager  
[scott@sonorawestdev.com](mailto:scott@sonorawestdev.com)  
Office : 602-667-3145  
Mobile : 602-980-1145  
Fax : 602-667-3158

---

**Additional Company/Contact** - Sonora West Development, Inc.  
8937 E Bell Road, Ste. 100  
Scottsdale, AZ 85260  
[www.sonorawestdev.com](http://www.sonorawestdev.com)  
Office : 602-667-3145  
Fax : 602-667-3158

---

**Mr. Scott Pfeiffer**  
President  
[scott@sonorawestdev.com](mailto:scott@sonorawestdev.com)  
Office : 602-667-3145  
Mobile : 602-980-1145  
Fax : 602-667-3158

---

DALLAS AIRMOTIVE, INC.

8853 E Desert Verbena  
Tucson, AZ 85715  
/ [www.dallasairmotive.com](http://www.dallasairmotive.com)

CITATION CJ2 SN #525A-0085

